



## State of Utah

## Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Richard Safley					
OGM	Karl Houskeeper Environmental Scientist III					

# **Inspection Report**

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Friday, July 14, 2006
Start Date/Time:	7/14/2006 8:00:00 AM
End Date/Time:	7/14/2006 11:00:00 AM
Last Inspection:	Thursday, June 15, 2006

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Sunny/Clear, Temp. 91 Deg. F. InspectionID Report Number: 1007

✓ Reprocessing

Accepted by: pgrubaug

7/19/2006

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

<b>Current Acreages</b>		Mineral Ownership	<b>Types of Operations</b>		
152.81	Total Permitted	☐ Federal			
88.78	Total Disturbed	☐ State	☐ Surface		
	Phase I	☐ County	☐ Loadout		
	Phase II	<b>✓</b> Fee	☐ Processing		
88.78	Phase I	County	☐ Loadout		

☐ Other

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending actions: No pending actions.

Inspector's Signature:

**Date** 

Friday, July 14, 2006

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Friday, July 14, 2006

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
  2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		$\checkmark$	
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓	<b>✓</b>		
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	<b>✓</b>		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>		<b>✓</b>	
8.	Noncoal Waste	<b>✓</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				П

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Friday, July 14, 2006

Page 3 of 3

### 1. Permits, Change, Transfer, Renewal, Sale

Pending actions: No pending actions.

#### 2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

The ID sign on the west side of the public access into the permit area had been reinstalled, but had blown loose again. Richard Safley is going to obtain materials and re-secure the sign to give it more strength.

### 7. Coal Mine Waste, Refuse Piles, Impoundments

Mining was occuring on top of the refuse pile in lifts from the east to the west. No visible hazards were noted. Culvert that was removed from the diversion repair in June is still ontop of the refuse pile and should be removed.

#### 8. Noncoal Waste

See item 7 (Culvert).